


## WIRING CONFIGURATION FOR HIRSCHMANN CONNECTORS







## **DANGER**

THE MOTOR CABLE CONNECTOR (STAS 3) <u>MUST NOT</u> BE USED ON THE SUPPLY CABLE.

THIS MAY CAUSE SERIOUS INJURY OR ELECTROCUTION.

